

INVENTARISASI DATABASE INDEKS KUALITAS UDARA

NO	LOKASI				Nilai Indeks Kualitas Udara
1	PTPN VIII	Rancabali	Rona Awal	7°09'17.6"S 107°21'53.2"E	79.913
2	Situ Cisanti	Kertasari	Rona Awal	7°12'30.4"S 107°39'36.8"E	85.278
3	Situ Cileunca	Pangalengan	Rona Awal	7°11'41.4"S 107°32'46.7"E	79.427
4	Kantor Kelurahan Rancaekek	Rancaekek	Pemukiman	6°58'30.4"S 107°45'26.6"E	68.420
5	SDN Maruyung	Pacet	Pemukiman	7°06'52.3"S 107°42'04.3"E	76.042
6	Kantor Desa Pinggirsari	Arjasari	Pemukiman	7°03'26.8"S 107°39'11.7"E	74.826
7	RSUD Cicalengka	Cicalengka	Komersil/Perkantoran	6°58'56.9"S 107°50'28.8"E	88.073
8	RSUD Majalaya (EBAH)	Paseh	Komersil/Perkantoran	7°02'55.8"S 107°46'19.8"E	66.493
9	Kantor Kecamatan Ibun	Ibun	Komersil/Perkantoran	7°06'01.9"S 107°45'51.3"E	74.306
10	Kantor Kecamatan Nagreg	Nagreg	Transportasi	7°00'53.5"S 107°52'40.8"E	69.907
11	Tol Soroja (Keluar Gerbang Tol Soreang)	Soreang	Transportasi	7°00'47.7"S 107°31'54.0"E	74.132
12	Alun-alun Ciwidey	Ciwidey	Transportasi	7°06'11.1"S 107°27'45.6"E	80.208
13	PT. Stanli Trijaya Mandiri	Katapang	Industri	6°59'27.6"S 107°33'13.2"E	77.431
14	PT. Gistex Margaasih	Margaasih	Industri	6°56'14.8"S 107°32'11.9"E	67.535
15	PT. Bozzeto Indonesia	Banjaran	Industri	7°02'39.6"S 107°34'50.5"E	65.799
IKU Total					75.186